




Overview: Part of spill impact on 24" Nkpoku-Bomu Pipeline Right of Way at Egbalor. Picture was taken during Joint Investigation of 14th June 2018.



Close-up: Illegal fitting on 24" Nkpoku-Bomu Pipeline at Egbalor. . Picture was taken during Joint Investigation of 14th June 2018.