


Overview: Part of spill impact on Okordia Manifold at Ikarama. Picture was taken during Joint Investigation of 13th June 2018.



Close-up: Cut/Punctured Elbow on Okordia Manifold at Ikarama. Picture was taken during Joint Investigation of 13th June 2018.