





Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline Right of Way at Odau KM9. Picture was taken during Joint Investigation of 4th July 2018.



Close-up: Leak point from 2" pipe extension on 20" Kolocreek-Rumuekpe Pipeline at Odau KM9. Picture was taken during Joint Investigation of 3rd July 2018.



Close-up: Illegal Fitting on 20" Kolocreek-Rumuekpe Pipeline at Odau KM9. Picture was taken during Joint Investigation of 3rd July 2018.