


Overview: Part of spill impact on 8'' Obigbo North – New Elenwa Pipeline Right of Way at Umusonaya. Picture was taken during Joint Investigation of 9th June 2019.



Close-up: Illegal fitting on 8'' Obigbo North – New Elenwa Pipeline at Umusonaya. Picture was taken during Joint Investigation of 9th June 2019