




Overview: Part of spill impact on 14" Okordia – Rumuekpe Pipeline Right of Way at Oshie. Picture was taken during Joint Investigation of 17th June 2019.



Close-up: Illegal Fitting on 14" Okordia – Rumuekpe Pipeline at Oshie. Picture was taken during Joint Investigation of 17th June 2019