





**Overview:** Part of spill impact on 4" Obele – Ibaa Pipeline Right of Way at Ibaa Picture was taken during Joint Investigation of 14<sup>th</sup> June 2019.



**Close-up:** Hack Saw Cut on 4" Obele – Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 14<sup>th</sup> June 2019.



Close-up: Hack Saw Cut on 4'' Obele – Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 14<sup>th</sup> June 2019.