




Overview: Part of spill impact on 12'' Imo River – Ogale Pipeline Right of Way at Owaza. Picture was taken during Joint Investigation of 22nd June 2019.



Close-up: Plugged Illegal Fitting on 12'' Imo River – Ogale Pipeline at Owaza. Picture was taken during Joint Investigation of 22nd June 2019