




**Overview:** Part of spill impact on 14" Okordia-Rumuekpe Pipeline Right of Way at Akara-Olu. Picture was taken during Joint Investigation of 11<sup>th</sup> June 2019.



**Close-up:** Hack Saw Cut on 14" Okordia-Rumuekpe Pipeline at U Akara-Olu. Picture was taken during Joint Investigation of 11<sup>th</sup> June 2019.