




**Overview:** Part of spill impact on 24" Nkpoku-Bomu Pipeline Right of Way at Egbalor. Picture was taken during Joint Investigation of 20<sup>th</sup> June 2018.



**Close-up:** Hack Saw Cut on 24" Nkpoku-Bomu Pipeline at Egbalor. . Picture was taken during Joint Investigation of 20<sup>th</sup> June 2018.