



Overview: Part of spill impact on 28'' Nkpoku - Bomu Pipeline Right of Way at Ejamah – Ebubu. Picture was taken during Joint Investigation of 27th June 2019.



Close-up: Illegal fitting on 28'' Nkpoku - Bomu Pipeline at Ejamah – Ebubu. Picture was taken during Joint Investigation of 27th June 2019.