



Overview: Part of spill impact on 28" Nkpoku Bomu Pipeline at Rumuowha. Picture was taken during Joint Investigation 7th June 2020.



Close-up: 3 nos 2" valves installed at 12 o'clock position on 28" Nkpoku Bomu Pipeline at Rumuowha. Picture was taken during Joint Investigation 7th June 2020.