




Overview: Part of spill impact on New 20'' Kolocreek - Rumuekpe Pipeline at Okoma 1 . Picture was taken during Joint Investigation 16th June 2020.



Close-up: Tampered clamp on New 20'' Kolocreek - Rumuekpe Pipeline at Okoma 1 . Picture was taken during Joint Investigation 15<sup>th</sup> June 2020