




Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation 18th June 2020.



Close-up: Plugged Crude Oil theft point installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation 18th June 2020.