



Overview: Part of spill impact on 8" Nkali - ImoRiver Deliveryline at Odagwa. Picture was taken during Joint Investigation 18th June 2020.



Close-up: 1.5" bulb valve installed at 12 o'clock position on 8" Nkali - ImoRiver Deliveryline at Odagwa. Picture was taken during Joint Investigation 18th June 2020.