



Overview: Part of spill impact on 28" Bomu Bonny Pipeline at Kpor. Picture was taken during Joint Investigation of 11th June 2020.



Close-up: Hack saw cut of 4m at 3 o'clock position on 28" Bomu Bonny Pipeline at Kpor. Picture was taken during Joint Investigation of 13th June 2020.