



Overview: Extent of the spill incident impact on 16" Egbema-Assa Pipeline at Assa . Pictures taken during Joint Investigation of 4th March, 2011



Close-up: Spill due to illegally welded points on 16" Egbema-Assa Pipeline at Assa. Picture taken during Joint Investigation of 4th March, 2011 .