



Overview: Extent of the spill incident impact at 24'/28' Bomu-Bonny Pipeline at Bodo West. Picture was taken during JIV of 10 March 2011.



Close-up: Illegally welded points on 24' Bomu-Bonny Pipeline at Bodo West. Insert showing illegally welded points on 28' Bomu-Bonny Pipeline at Bodo West. Pictures taken during JIV of 10 March 2011.