



Overview: Extent of the spill incident impact at 20' Kolocreek-Rumuekpe Pipeline at Ogbogolo. Insert showing bunkering hoses from the site. Picture was taken during JIV of 11 March 2011



Close-up: Illegally welded point on 20' Kolocreek-Rumuekpe Pipeline at Ogbogolo. Picture was taken during JIV of 12 March 2011