



Overview: Extent of the spill incident impact at Imo River 1 Well 59T flowline right of way.
Picture was taken during JIV of 15 March 2011



Close-up: Illegally welded point on Imo River 1 Well 59T Flowline. Picture was taken during JIV of 15 March 2011