



Overview: Extent of the spill incident impact on 24in Bomu-Bonny pipeline at Bodowest. Spill site showing oil theft hose still attached to illegal off take point.



Close-up: Picture showing illegally welded points on 24in Bomu-Bonny pipeline at Bodowest. Spill site showing oil theft hose still attached to illegal off take point.



Overview: Extent of the spill incident impact on 28in Bomu-Bonny pipeline at Bodowest. Spill site showing oil theft hoses still attached to illegal off take points.



Close-up: Picture showing illegally welded points on 28in Bomu-Bonny pipeline at Bodowest. Picture taken during Joint Investigation of 29th March, 2011.