




Overview: Part of spill impact on 16" Nun River – Kolo Creek trunkline right of way at Angiama-Gbeni. Picture was taken during Joint Investigation of 17th March 2012.



Close up: Hacksaw cut on 16" Nun River – Kolo Creek trunkline at Angiama-Gbeni. Picture was taken during Joint Investigation of 19th March 2012.