



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at Bera.
Picture was taken during Joint Investigation of 27th March 2012.



Close up: Hacksaw cut on 24" Nkpoku-Bomu pipeline at Bera. Picture was taken during Joint Investigation of 27th March 2012.