



Overview: Part of spill impact on 8" Isimiri pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 21st March, 2012.



Close-up: Illegal fitting on 8" Isimiri pipeline at Obiakpu. Picture was taken during Joint Investigation of 20th March, 2012.