



Overview: Part of spill impact on Ubie Well9S flowline right of way at Idu-Ekpeye. Picture was taken during Joint Investigation of 4th April 2012.



Close up: Cut section on Ubie Well9S flowline at Idu-Ekpeye. Picture was taken during Joint Investigation of 4th April 2012.