



Overview: Part of spill impact on 4" Cawthorne Channel 1 Well 49 Flow line at Mbiama. Picture was taken during Joint Investigation of 24th April 2013.



Close up: Missing Flow line on 4" Cawthorne Channel 1 Well 49 Flow line at Mbiama. Picture was taken during Joint Investigation of 24th April 2013.