



Overview: Part of spill impact on 12" Imo River2 pipeline right of way at Odagwa. Picture was taken during Joint Investigation of 10th March 2013.



Close up: Illegal fitting on 12" Imo River2 pipeline at Odagwa. Picture was taken during Joint Investigation of 10th March 2013.