



Overview: Part of spill impact on 8" Umuechem – Nkpoku pipeline right of way at Umuwenye. Picture was taken during Joint Investigation of 3rd March 2013.



Close up: Illegal fitting on 8" Umuechem – Nkpoku pipeline at Umuwenye. Picture was taken during Joint Investigation of 3rd March 2013.