




Overview: Part of spill impact on 36" Nkpoku-Bomu Trans Niger Pipeline Right of Way at Rumuchiolu/Eneka. Picture was taken during Joint Investigation of 22nd March 2016.



Close-up: Illegal fittings on 36" Nkpoku-Bomu Trans Niger Pipeline at Rumuchiolu/Eneka. Picture was taken during Joint Investigation of 22nd March 2016.