



Overview: Part of spill impact on 20" KoloCreek – Rumuekpe Trans Niger Pipeline Right of Way at Odau. Picture was taken during Joint Investigation of 7th April 2016



Close-up: Illegal fitting on 20" KoloCreek – Rumuekpe Trans Niger Pipeline at Odau. Picture was taken during Joint Investigation of 7th April 2016.