



Overview: Part of spill impact on 8"Belema-Sego Delivery line at Offoinama. Picture was taken during Joint Investigation of 16th March 2016.



Close-up: Plugged drilled hole on 8"Belema-Sego Delivery line at Offoinama. Picture was taken during Joint Investigation of 22nd August 2016.