




Overview: Part of spill impact 12" Imo River-Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 7<sup>th</sup> March 2017.



Close-up: Leaking Illegal fitting on 12" Imo River-Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 8<sup>th</sup> March 2017.