



Overview: Part of spill impact 28" Bomu-Bonny Trans Niger Pipeline at Owokiri. Picture was taken during Joint Investigation of 19th March 2017



Close-up: Illegal fitting on 28" Bomu-Bonny Trans Niger Pipeline at Owokiri. Picture was taken during Joint Investigation of 19th March 2017.