



Overview: Part of spill impact on 4" Obele-Ibaa Pipeline Right of Way at Ibaa. Picture was taken during Joint Investigation of 23rd March 2017.



Close-up: Hacksaw cut on 4" Obele-Ibaa Pipeline at Ibaa. Picture was taken during Pipeline Repair on 24th March 2017.