



Overview: Part of spill impact on 16" Egbema - Assa Pipeline at Obile . Picture was taken during Joint Investigation of 26<sup>th</sup> March 2018.



Close-up: Hacksaw Cut on 16" Egbema - Assa Pipeline at Obile . Picture was taken during Joint Investigation of 26<sup>th</sup> March 2018.