



Overview: Part of spill impact on Ukpeliède Manifold at Ukpeliède. Picture was taken during Joint Investigation of 6th April 2018.



Close-up: Tampered 2" Inlet Pressure Gauge & 2" Inlet Vent Valves on Ukpeliède Manifold at Ukpeliède. Picture was taken during Joint Investigation of 6th April 2018.