




Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 12th April 2018.



Close-up: Hacksaw Cut and Inward dent on 14" Okordia-Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 23rd April 2018.