



Overview: Part of spill impact on 12" Oguta – Egbema Pipeline at Eziorsu. Picture was taken during Joint Investigation of 19th March 2020.



Close-up: 2" valve installed at 12 o'clock position on 12" Oguta – Egbema Pipeline at Eziorsu. Picture was taken during Joint Investigation of 19th March 2020.