




Overview: Part of spill impact on 28" Nkpoku Bomu Pipeline at Eteo. Picture was taken during Joint Investigation of 26th March 2020.



Close-up: 1" valve installed at 12 o'clock position on 28" Nkpoku Bomu Pipeline at Eteo. Picture was taken during Joint Investigation of 26th March 2020.