



Overview: Part of spill impact on 4" Etelebou Well 1S Flowline at Ogboloma. Picture was taken during Joint Investigation of 18th March 2020.



Close-up: 4" Etelebou Well 1S Flowline at Ogboloma. Picture was taken during Joint Investigation of 18th March 2020.



Close-up: Pen size hole at 6 O'clock position on 4" Etelebou Well 1S Flowline at Ogboloma.
Picture was taken during Post visit of
22nd March 2020.