



Overview: Part of spill impact on NunRiver Well 13T Well head at Angiama. Picture was taken during Joint Investigation of 28<sup>th</sup> March 2020.



Close-up: Erosion on bean box on NunRiver Well 13T Well head at Angiama. Picture was taken during Joint Investigation of 28<sup>th</sup> March 2020.