



Overview: Part of spill impact on Old 20" Kolocreek – Rumuekpe Pipeline at Odau-KP9. Picture was taken during Joint Investigation of 21st March 2020.



Close-up: Crude oil theft points at 12 o'clock position on Old 20" Kolocreek – Rumuekpe Pipeline at Odau-KP9. Picture was taken during Joint Investigation of 21st March 2020.



Close-up: Crude oil theft points at 12 o'clock position on Old 20" Kolocreek – Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 21st March 2020.