



Overview: Part of spill impact on 8" Cawthorne Channel 2 delivery line right of way at Tigerkiri. Picture was taken during Joint Investigation of 27th July 2012.



Close up: Illegal fitting on 8" Cawthorne Channel 2 delivery line at Tigerkiri. Picture was taken during Joint Investigation of 29th July 2012.