



Overview: Part of spill impact on 18" Assa-Rumuekpe pipeline right of way at Egbeda. Picture was taken during Joint Investigation of 30th May 2012.



Close up: Hacksaw cut on 18" Assa-Rumuekpe pipeline at Egbeda. Picture was taken during Joint Investigation of 30th May 2012.