



Close up: Illegal fitting on 28" Bomu-Bonny TransNiger pipeline at Bodo West.
Picture was taken during Joint Investigation of 24th May 2013.