



Overview: Part of spill impact on 6" Obigbo North – KomKom pipeline right of way at KomKom. Picture was taken during Joint Investigation of 22nd May 2013.



Close up: Illegal fittings on 6" Obigbo North – KomKom pipeline at KomKom. Picture was taken during Joint Investigation of 22nd May 2013.