



Overview: Part of spill impact on 8" Ubie-Ukpeliede pipeline right of way at Idu-Ekpeye. Picture was taken during Joint Investigation of 18th May 2013.



Close up: Spill due to hacksaw cut on 8" Ubie-Ukpeliede pipeline at Idu-Ekpeye. Picture was taken during Joint Investigation of 18th May 2013.