




Overview: Part of spill impact on 12" Oguta-Egbema pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 22nd May 2013.



Close up: Drilled holes on 12" Oguta-Egbema pipeline at Obiakpu. Picture was taken during Joint Investigation of 23rd May 2013.