



Close up: Illegal fitting on 24" Bomu-Bonny Trans Niger pipeline at BodoWest. Picture was taken during Joint Investigation of 2<sup>nd</sup> June 2013.



Close up: Section with coating removed on 24" Bomu-Bonny Trans Niger pipeline at BodoWest. Picture was taken during Joint Investigation of 4<sup>th</sup> June 2013.