



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at Egbalor. Picture was taken during Joint Investigation of 26th May 2013.



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at Egbalor. Illegal hoses can be seen connected to illegal bunkering point.



Close up: Illegal fitting on 24" Nkpoku-Bomu pipeline at Egbalor. Picture was taken during Joint Investigation of 26th May 2013.