



Overview: Part of spill impact on 28" Bomu-Bonny Trans Niger Pipeline Right of Way at Otokolomabie/Oloma. Picture was taken during Joint Investigation of 11th May 2015.



Close-up: Illegal fitting on 28" Bomu-Bonny Trans Niger Pipeline at Otokolomabie/Oloma. Picture was taken during Joint Investigation of 11th May 2015.